

11-09-07

CJC

**HARNESSES**  
**DICKEY**

10/822 821



November 8, 2007

**Express Mail Label**  
**No. EM 061 814 043 US**

Commissioner for Patents  
Mail Stop Issue Fee  
Alexandria, VA 22313-1450

**Certificate**

**DEC 0 5 2007**

**of Correction**

Re: U.S. Patent No. 7,260,948  
Issued August 28, 2007  
For: Compressor Diagnostic System  
Nagaraj Jayanth et al, Inventor

**EM 061 814 043 US**

Dear Sir:

We have noted, in proofreading the above-identified patent, the following typographical errors:

Column 4, line 10, "is" should be "its".

Column 6, line 1, "by-logic" should be - by logic --.

Column 6, line 5, "analyses" should be - analyzes --.

Column 7, line 29, "shortened" should be - shortened --.

Column 7, line 35, "shortened" should be - shortened --.

Column 8, line 50, "shortened" should be - shortened --.

Column 8, line 56, "shortened" should be - shortened --.

Column 10, line 47, "analyses" should be - analyzes --.

Column 13, line 25, delete "in".

Column 13, line 37, "compressure" should be - compressor --.

Harness, Dickey & Pierce, P.L.C.  
Attorneys and Counselors  
P.O. Box 828  
Bloomfield Hills, Michigan 48303 U.S.A.  
248.641.1600 • fax 248.641.0270


FOR COURIER DELIVERY ONLY  
5445 Corporate Drive, Suite 200  
Troy, Michigan 48098 U.S.A.

Metropolitan  
Detroit, MI St. Louis, MO Washington, D.C.

[www.hdp.com](http://www.hdp.com)

Kindly make these errors of record in your files.

Very truly yours,

By 

Michael Malinzak  
Registration No. 43770  
Attorney for Applicant

MM/d  
0315-000510/COE